





Only use PPE that is designed for the task being done.

Always inspect/test all PPE before you use it.

Use a protective outer cover if the work being performed could possibly damage the PPE's insulation.

Wear nonconductive headgear if there is danger of electrical burns/shock from contact with exposed, energized equipment.

Wear eye/face protection **anytime** there is danger of flying objects, flashes or electrical arcs produced by an electrical explosion.

